## eme134-l08-p01

Friday, October 12, 2018 5:43 AM

$$a_0 s^n + a_i s^{n-1} + \dots + a_n = 0$$

X(t) ± I e st

$$b_1 = \frac{a_1 a_2 - a_0 a_3}{a_1}$$

$$C_{3} = \frac{b_{1}a_{7} - a_{1}b_{4}}{b_{1}}$$

Bouth's criteria

- # of nots with positive real parts is equal to # of changes in sign of the ovefficients of the first column in the table
- necessary and sufficient condition for all roots to have regative real parts is for coefficients an to be positive and all terms in first column of table are positive

root has + real part => system un stable!


$$a_0 s^3 + a_1 s^2 + a_2 s + a_3 = 0$$

$$S^2$$
  $a_i$ 



$$\frac{a_1 a_1 - a_0 a_3}{a_1} < 0 \Rightarrow \text{unstable}$$

$$S^{\prime} \frac{\alpha_{1}\alpha_{2} - \alpha_{0}\alpha_{3}}{\alpha_{1}} \bigcirc$$



 $\frac{B_{raking}}{S_B} = \frac{U - r\omega}{U}$   $S_B = \frac{U - r\omega}{U}$   $W = r\omega \Rightarrow \text{free rolling}$   $W = r\omega \Rightarrow \text{free rolling}$   $S_B = 0$   $\frac{accel}{S_D} = \frac{r\omega - U}{r\omega}$   $S_D = \frac{r\omega - U}{r\omega}$ 

Case

eme134-l08 Page 4